

P C Home Inspection

Property Inspection Report



185 Fairgreen, Fullerton, CA 92833

Inspection prepared for: John Fairford

Date of Inspection: 12/18/2025

Age of Home: 48 Size: 2565 sf

Weather: Sunny
Inspector: Peter Chung

1065 Lomita Blvd, West Carson, CA 90710

Phone: 7145780046

Email: peter.chung@pchomeinspction.com

Table Of Contents

Table Of Contents

Report Summary	3
Overview	4
House Photos	4
Grounds	5-7
Roof	8-9
Exterior	10
Bathroom 1	11-14
Glossary	15

Report Summary



Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Grounds

Page 6 Item: 6	Deck/Porch/Patio Covers	

Roof

Page 9 Item: 7	Condition of Roof Covering	• One or more broken/loose tiles exist on the roof. Recommend a licensed roofer to replace the damaged tiles.

Overview

1. Scope of Inspection

- All components designated for inspection in the CREIA Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report. It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind. Please refer to the pre-inspection contract for a full explanation of the scope of the inspection. The professional home inspection is a visible, non-invasive inspection of the home on the day of the inspection only.

2. Main Entrance Faces

- For the purpose of this inspection, this house faces east.

3. State of Occupancy

- Occupied

4. Weather Conditions

- Sunny

5. Recent Rain/Snow

- No

6. Ground Cover

- Dry

7. Approximate Age

- Older

House Photos

1. House Photo's

Observations:

- The front of the house
- The side of the house
- The back of the house



House Photos (continued)



Grounds

1. Service Walks



Materials

- Concrete
- Condition
- Typical cracks

2. Driveway/Parking



Materials:

- Concrete
- Condition
- Typical cracks

3. Porch



Materials:

- Concrete
- Observations:
- The Porch View



4. Steps/Stoop



Materials:

- Concrete

Grounds (continued)



5. Patio



Materials:

- Concrete

Condition:

- Typical cracks

Observations:

- The Patio View



6. Deck/Porch/Patio Covers



Grounds (continued)



7. Fence/Wall

Materials:

- Block



8. Landscape Affecting Foundation

- Negative grade: Satisfactory



9. Retaining Wall



10. Hose Bibs

Hose Bibs:

- Yes, operable

Condition:

- Recommend anti-siphon valve

Observations:

- At least one hose bib is not equipped with an anti-siphon device. A possible cross-contamination can occur, which is a potential safety concern. A licensed plumber should install an anti-siphon/vacuum breaker.

- Hose bib operational.



Roof

1. Roof View

Roof View:

- The Roof View
- The Roof View



2. Roof General: Visibility

Visibility:

- Limited by: Height

Inspected From:

- Ladder at eaves
- Ground
- With binoculars

3. Roof Style: Type/Style

Type/Style:

- Tile

Layers/Age/Location:

- Unknown

4. Ventilation System

Type:

- Soffit
- Ridge

Observations:

- The Soffit Vent
- The Ridge Vent

5. Flashing



Materials:

- Galv/Alum

Condition:

- Separated from chimney/roof

Roof (continued)

6. Valleys

Materials:

- Not visible

Observations:

- The roof **valleys** inspection is limited to the visual portion of the valleys. There is always the potential for hidden damage in non visible areas. Recommend monitoring and consulting a licensed roofer as needed.
- The roof **valleys** inspection is limited to the visual portion of the valleys. There is always the potential for hidden damage in non visible areas. Recommend monitoring and consulting a licensed roofer as needed.



7. Condition of Roof Covering



Condition:

- Broken/Loose tiles/Shingles
- Recommend roofer evaluate

Observations:

- One or more broken/loose tiles exist on the roof. Recommend a licensed roofer to replace the damaged tiles.



8. Skylights



9. Vents



Condition:

- Not visible

Roof (continued)



Exterior

1. Chimney Chase

General:

- Location: West Side of Roof
- Rain Cap/Spark Arrestor: Yes

Observations:

- Evidence of: No apparent defects



2. Gutters

Materials:

- Galvanized/Aluminum



Exterior (continued)



3. Siding

Materials:

- Stucco
- Condition:
- Typical cracks

4. Trim

Materials:

- Wood

5. Fascia

Materials:



- Wood

6. Windows/Screens

Materials:

- Vinyl

7. Slab-On-Grade Foundation

Materials/Condition:

- Not visible

8. Service Entry

Location:

- Underground

9. Exterior Receptacles


Receptacles/Condition:



- Exterior receptacles: Yes
- Exterior receptacles, operable: Yes
- **GFCI** present: Yes

Bathroom 1




1. Sinks




2. Shower/Bathtub Area



Photos







Glossary

Term	Definition
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.
Valley	The internal angle formed by the junction of two sloping sides of a roof.